

Calgary Office

Ph: (403) 255-5222 | Fax: (403) 253-4448
7523 Flint Road SE, Calgary, AB T2H 1G3

info@tundrasolutions.ca

Edmonton Office

Ph: (780) 482-3444 | Fax: (780) 451-6422
11203 186 Street, Edmonton, AB T5S 2T7

www.tundrasolutions.ca



Please visit our WEB Site www.tundrasolutions.ca

QUARTERLY OR MONTHLY EXTERNAL SERVICES

- [] Visually inspect linkage, and proper operation.
- [] Test low water cutoffs.
- []. Check high and low gas pressure interlocks.
- [] Check burner and test flame failure controls.
- []. Check amperage draw on blower motor.
- []. Check oil control valves and switches.
- []. Fire Boilers on Diesel
- []. Check all door bolts for tightness. Customer will need to re-tighten door bolts periodically.
- []. Submit written report of services performed.

ANNUAL INTERNAL SERVICE

Services Performed Include –

- [] Includes services performed on the Quarterly visit.
- [] Open both fireside and waterside of boiler.
- [] Visibly check both fireside and waterside for cracking, pitting, corrosion, erosion and scale.
- []. Check tube sheets and tubes for evidence of water leakage.
- []. Check condition of refractory in doors and burner throat.
- []. Repair minor cracks in refractory and washcoat as needed.
- []. Install new gaskets and seal fireside and waterside.
- [] Perform leakage tests on pilot and main gas or fuel valves as per manufacturer's instructions
- [] Check combustion efficiency on one fuel and adjust air-fuel controls for optimum efficiency.
- [] Re-certify safeties if required.
- [] Meet with ABSA inspector on site if required
- [] Submit written report of services performed.